

OPTISONIC 7300 F

Ultrasonic process gas flowmeter remote version



Installation, assembly, start-up and maintenance may only be performed by appropriately trained personnel. Check the nameplate for correct operating conditions.



This instrument complies with requirements of Low Voltage Directive. Instruments must not be connected to power supply before reading instructions described in the manual.



This instrument complies with the requirements of Pressure Equipment Directive. Please refer to the nameplate for operating condition limits. Instruments must not be pressurised before reading instructions described in the manual.



The responsibility as to the suitability, intended use and corrosion resistance of the used materials against the measured fluid of this device rests solely with the operator.



For use in hazardous areas, special codes and regulations are applicable. Instruments must not be connected to power supply before reading instructions described in the supplementary manual.

Special conditions to be observed

- For ambient and process temperatures, specific product and electrical data, see Ex manual or certificate.
- For dimensions and details of the flameproof joints, the manufacturer shall be contacted.
- The tensile strength of the special fasteners is at least 700 N/mm² (property class A2-70 / A4-70).
- The instructions provided with the product shall be followed in detail to assure safe operation.

Ex ▶ Type Examination Certificate: KIWA 18 ATEX 0005 X / IECEx KIWA 18.0004 X
KIWA 17ATEX0002X / IECEx KIWA 17.0001X
UKCA: CSAE 22UKEX1360X / CSAE 22UKEX1288X

General

OPTISONIC 7000




T_a = -40...+70°C / -40...+158°F
T_p = -45...+180°C / -49...+356°F

Maximum ambient and process temperatures are depending on version (e.g liner material, size), temperature and protection class and maximum surface temperature of sensor.



Device nameplate




Check the device nameplate to ensure that the device is delivered according to your order.

1 Installation

Inlet, outlet and T-section




Installation instructions for ≥ DN100/4"
(2 measuring path)
Consult the manual for DN50...80/ 2..3"
(1 measuring path).



▶ see below "2D and 3D bends"

XY (2D bends upstream) : ≥ 10 × Ø



XYZ (3D bends upstream) : ≥ 15 × Ø



Check the manual for more details on installation options.





Installation position




Dry gas only!


+15° < α < -15°

Biogas version






Avoid vibration



Pipe mounting

Wall mounting

Thermal insulation



① Leave vent holes free

2 Electrical connection



All work on the electrical connections may only be carried out with the power disconnected. Take note of the voltage data on the nameplate! Observe the national regulations for electrical installations!




Observe without fail the local occupational health and safety regulations. Any work done on the electrical components of the measuring device may only be carried out by properly trained specialists.




The device must be grounded in accordance with regulations in order to protect personnel against electric shocks.

Electrical connections signal converter



Power supply - grounding



- ① 100...230 VAC (-15% / +10%), 22VA
- ② 24VDC (-55% / +30%), 12W
- ③ 24VAC/DC (AC: -15% / +10%; DC: -25% / +30%), 22VA or 12W

- ① Sensor cable connections
- ② I/O connections
- ③ Mains supply connection
- ④ Insert cable(s) into terminal compartment
- ⑤ Marking on cable
- ⑥ Tool for releasing connectors
- ⑦ Grounding clamps



Connect the cable on connector with similar numeral marking



Avoid the risk of ignition as a result of electrostatic charging. Do not use the device in areas, with processes that generate high charges, with mechanical friction and cutting process, near electrostatic painting systems (spraying of electrons), with exposure of airborne powder or dust particles (pressurized systems).

2 Electrical connection




For devices used in hazardous areas, additional safety notes apply; please refer to the Ex documentation.

Refer to the manual for connection of Ex (i) acc. to NAMUR





Connect the cable on connector with similar numeral marking

Signal cable to flow sensor




Standard version


Connection diagram




Current output active Ia (basic I/O)




Current output passive Ip (basic I/O)




Pulse/frequency output passive Pp (basic I/O)




Status output/limit switch passive Sp (basic I/O)




Control input passive Cp (basic I/O)



Current output active Ia (modular/Ex i I/O)




Current output passive Ip (modular/Ex i I/O)




Pulse/frequency output active Pa (modular I/O)




Observe connection polarity




Pulse/frequency output passive Pp (modular I/O)




Pulse/frequency output passive PN, NAMUR (modular I/O)




Status output/limit switch active Sa, (modular I/O)




Status output/limit switch passive Sp, (modular I/O)




Status output/limit switch SN, NAMUR, (modular I/O)



Control input active Ca, (modular I/O)




Control input passive Cp, (modular/Ex i I/O)



Control input active CN to NAMUR, (modular I/O)

3 Quick Setup



Measuring mode			
Press > 2.5 s			
Select menu		Select Submenu	Functions
A Quick Setup	A1 language		
	A2 tag		
	A3 reset	A3.1 reset errors	
		A3.2 counter 1	
		A3.3 counter 2	
		A3.4 counter 3	
	A6 GDC IR interface		

Download documents/software
Scan the code on the nameplate or scan the following code and enter the serial number.



Contact

Select your country from the region / language selector to view your local KROHNE contact details on:
www.krohne.com