

Spare parts list

Bosch Rexroth AG
Service Hydraulics
Bgm.-Dr.-Nebel-Str. 8
97816 Lohr
Germany

Material number: R039033504
Drawing:
Designation: BELT DRIVE GEAR
BELT DRIVE GEAR MS2N03-B I=1

Status of version: 04/2024

Date: 23.04.2024

Page: 1

Pos.	Material number	Designation	Tech.Pos.	Quantity
20	R039630008	PULLEY WHEEL PULLEY WHEEL AT3, Z = 48, B = 23		1000 UNIT
30	R039630010	PULLEY WHEEL PULLEY WHEEL AT3, Z = 48, B = 15		1000 UNIT
100	R345401082	CLAMPING PARTS SET CLAMPING PARTS SET 11-22		1000 UNIT
110	R345401100	CLAMPING PARTS SET CLAMPING PARTS SET 9-20		1000 UNIT
120	R345401103	TOOTHED BELT TOOTHED BELT 10 AT3 351 MM		1000 UNIT

L = Assembly group D = Sealing element

Security notice:

Assembly, commissioning and operation, disassembly, service (including maintenance and repair) require basic mechanical/electrical/hydraulic/pneumatic knowledge, as well as knowledge of the appropriate technical terms. In order to ensure operating safety, these activities may therefore only be carried out by qualified technical personnel or an instructed person under the direction and supervision of qualified personnel. Qualified personnel are those who can recognize possible hazards and institute the appropriate safety measures due to their professional training, knowledge, and experience, as well as their understanding of the relevant conditions pertaining to the work to be done. Qualified personnel must observe the rules relevant to the subject area. Also observe the generally applicable, legal or otherwise binding regulations of the European or national legislation and the rules for the prevention of accidents and for environmental protection applicable in your country. The data specified above only serve to describe the product. No statements concerning a certain condition or suitability for a certain application can be derived from our information. The given information does not release the user from the obligation of own judgement and verification. It must be remembered that our products are subject to a natural process of wear and aging.

©This document, as well as the data, specifications and other information set forth in it, are the exclusive property of Bosch Rexroth AG. Without their consent it may not be reproduced or given to third parties.